



Figure 3.73. Corner break for US-64 (2) sections; (a) none rating, (b) light rating, (c) moderate rating, and (d) severe rating.

3.5.7.3. Discussion

Reference survey

- The highest corner break content is at I-440-16, I-40-301, and I-40-300, 10-15%. For I-440-16 this is mostly light severity breaking but for the other two sections it is mostly moderate.
- Very slight light and moderate corner breaking (2% for both) is observed at US-64-13.

Pathway Services

- Overall little corner breaking is counted.
- The highest concentration of counted breakage is at I-440-16 and is approximately 15% light severity breakage.
- US-64 sections show no corner breaking.

Fugro Roadware

- Overall little corner breaking is counted except for I-440-15.
- The highest concentration of counted breakage is at I-440-16 and is approximately 70% light severity breakage. Other than this section, I-440-16 shows approximately 15% light severity breakage.
- US-64 sections show no corner breaking.